

H0171

LUM-BRITE

ACID TYPE ALUMINUM CLEANER FOR POTS & PANS

Restores brightness and luster to aluminum pots & pans



DESCRIPTION:

For general cleaning of aluminum pots & pans and all aluminum surfaces where baked on carbon and stains are a problem.

DIRECTIONS:

For light cleaning: Use 4 ounces per gallon of water. **For heavy cleaning:** Use 6 ounces per gallon of water. Mix solution in plastic receptacle and allow to soak until soil is released. Remove sludge with sponge and regular detergent. Pots & Pans may be burnished with a steel wool soap pad for high luster.

PRECAUTIONARY STATEMENTS:

Wear gloves and protective eyewear. If swallowed: rinse mouth. Do NOT induce vomiting. If on skin (or hair): Take off immediately all contaminated clothing. Rinse skin with water/shower. If inhaled: Remove person to fresh air and keep comfortable for breathing. If in eyes: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. Immediately call a physician. Wash contaminated clothing before reuse.



PHYSICAL PROPERTIES

APPEARANCE: Clear colorless
liquid

Specific Gravity: 1.4

Odor: Pungent

pH: < 1

Solubility in water:: Complete

PACKAGING

Stocked in quarts and
gallons.

Other sizes available.
Call for minimums

CleanPak Products LLC.

221 Hobbs St. Suite 108
Tampa, FL 33619
T 813-740-8611 - F 813-740-8218
admin@cleanpakproducts.com -
www.cleanpakproducts.com